

Human Health and Environmental Effects

Exposure Potential and Risk Mitigation Measures

Carbon monoxide is shipped as a high pressure gas. Precautions should be taken based on shipment mechanism (pipeline, gas cylinders, tube trailers, etc.).

Use atmospheric and personal monitors to ensure carbon monoxide levels do not exceed occupational exposure limits.

Personnel should be trained on the hazards and risks of carbon monoxide and eliminate all ignition sources.

Precautions for the flammability of carbon monoxide include no smoking and the use of proper electrical equipment.